

Model 9208

Please save this sheet. This sheet is required in the event a scanner needs to be reprogrammed. Before reprogramming a scanner, please contact Edmunds GovTech Technical Services.

1



Enable Function Key Mapping

2



Scan Options

3



<DATA> <SUFFIX>

4



Enter